



Administrative Forest	Repair Needed	Other - See Comments	Aerial Retardant Drop	Drop Point	Internet Access
Wilderness Area	No Repair Needed	Unknown	Air Tanker Retardant	Dozer Push	Mobile Weather Unit
Administrative Forest	Other - See Comments	Contained Line	Road Repair	Fence - Cut/Damaged	Repair Point
Slate Mtn Botanical Area	Unknown	Completed Dozer Line	Other	Gate	Retardant in Avoidance Area
Repair Status	Completed - Inspected	Road as Completed Line	Backcountry Structures	Hazard	Road Repair
In Use - Fire Management	In Use - Fire Management	Access or Improved Road	Dip Site	Hazard Tree	Safety Zone
Completed - Ready for Inspection	In Progress	Completed Plow Line	Bridge	Helibase	Stream Crossing
In Progress	Repair Needed	Proposed Dozer Line	Closure	Retardant/Mud Pit	Water Source
In Progress	No Repair Needed	Fire Break Planned or Incomplete	Culvert	Value at Risk	Other
		Planned Fire Line		Private	Private

SUPPRESSION REPAIR South Ponderosa

SQF Complex
CA-SQF-002622
11/05/2020



170,866 acres,
as of 11/04/2020, 0900 HRS

0 0.15 0.3 0.45 0.6 Miles

1:12,000

Map Updated: 11/4/2020 7:47