



Administrative Forest	Repair Needed	Other - See Comments	Aerial Retardant Drop	Dozer Push	Mobile Weather Unit	BOR
Wilderness Area	No Repair Needed	Unknown	Air Tanker Retardant	Fence - Cut/Damaged	Repair Point	FS
Administrative Forest	Other - See Comments	Contained Line	Other	Gate	Retardant in Avoidance Area	FWS
Slate Mtn Botanical Area	Unknown	Completed Dozer Line	Backcountry Structures	Hazard	Safety Zone	NPS
<b>Repair Status</b>	Completed - Inspected	Completed Hand Line	Dip Site	Hazard Tree	Stream Crossing	State
Completed - Inspected	In Use - Fire Management	Road as Completed Line	Helibase	Helispot	Water Source	Private
In Use - Fire Management	Completed - Ready for Inspection	Access or Improved Road	Closure	Value at Risk	Wildfire Daily Fire Perimeter	Other
Completed - Ready for Inspection	In Progress	Completed Plow Line	Culvert	Other	Private	Private
In Progress	Repair Needed	Fire Break Planned or Incomplete	Internet Access	BIA	BLM	Private
In Progress	No Repair Needed	Planned Fire Line		BLM		

**SUPPRESSION REPAIR**  
**South Ponderosa**  
 SQF Complex  
 CA-SQF-002622  
 11/07/2020



171,032 acres,  
 as of 11/06/2020, 0900HRS

1:12,000  
 Map Updated: 11/6/2020 9:26