


SUPPRESSION REPAIR PONDEROSA

11/08/2020





Administrative Forest	In Progress	Repair Needed	Fire Break Planned or Incomplete	Drop Point	BLM
Wilderness Area	Repair Needed	No Repair Needed	Planned Fire Line	Dozer Push	BOR
Administrative Forest	No Repair Needed	Other - See Comments	Air Tanker Retardant	Gate	FS
Slate Mtn Botanical Area	Other - See Comments	Unknown	Other	Mobile Weather Unit	FWS
Repair Status	Unknown	Contained Line	Backcountry Structures	Repair Point	NPS
Completed - Inspected	Completed - Inspected	Completed Dozer Line	Dip Site	Safety Zone	State
In Use - Fire Management	In Use - Fire Management	Completed Hand Line	Stream Crossing	Closure	Private
In Use - Fire Management	Completed - Ready for Inspection	Road as Completed Line	Bridge	Wildfire Daily Fire Perimeter	Private
Completed - Ready for Inspection	In Progress	Completed or Improved Road	Closure	BIA	Private
In Progress		Proposed Dozer Line			

SUPPRESSION REPAIR
Ponderosa
 SQF Complex
 CA-SQF-002622
 11/08/2020



171,032 acres,
 as of 11/06/2020, 0900HRS



1:7,000

Map Updated: 11/6/2020 9:56