



Administrative Forest	Repair Needed	Other - See Comments	Aerial Retardant Drop	Dozer Push	Mobile Weather Unit	BOR
Wilderness Area	No Repair Needed	Unknown	Air Tanker Retardant	Fence - Cut/Damaged	Repair Point	FS
Administrative Forest	Other - See Comments	Contained Line	Other	Gate	Retardant in Avoidance Area	FWS
Slate Mtn Botanical Area	Unknown	Completed Dozer Line	Backcountry Structures	Hazard	Safety Zone	NPS
<b>Repair Status</b>	Completed - Inspected	In Use - Fire Management	Dip Site	Hazard Tree	Stream Crossing	State
In Use - Fire Management	Completed - Ready for Inspection	In Progress	Helibase	Helispot	Water Source	Private
Completed - Ready for Inspection	In Progress	Repair Needed	Bridge	Value at Risk	Fire Break Planned or Incomplete	Wildfire Daily Fire Perimeter
In Progress	No Repair Needed	Planned Fire Line	Closure	Culvert	Internet Access	Other
			Drop Point	BIA	BLM	Private

**SUPPRESSION REPAIR**  
**South Ponderosa**  
 SQF Complex  
 CA-SQF-002622  
 11/09/2020



171,031 acres,  
 as of 11/08/2020, 0900HRS

0 0.15 0.3 0.45 0.6 Miles  
 1:12,000  
 Map Updated: 11/7/2020 7:51