



SUPPRESSION REPAIR

KNP Complex
CA-KNP-000122
10/31/2021

1:50,000 - CIIMT 12 GIS - 10/31/2021 1051
 North American 1983 Datum, Lat/Long Grid

<ul style="list-style-type: none"> Repair Status Completed - Inspected In Use - Fire Management Completed - Ready for Inspection In Progress Repair Needed No Repair Needed Other - See Comments Unknown Helispot Helibase Sling Site Division Break 	<ul style="list-style-type: none"> Drop Point Camp Staging Area Value at Risk Other Gate Road Repair Retardant in Avoidance Area Repair Point Fence - Cut/Damaged Dozer Push Clean Up Area Safety Zone Water Tank 	<ul style="list-style-type: none"> Completed Dozer Line Completed Hand Line Access or Improved Road Highlighted Feature Other Repair Line Fire Edge Contained Line Structure Major Road Minor Road Unpaved Road Trail USFS Boundary 	<ul style="list-style-type: none"> NPS Wilderness USFS Wilderness Wild and Scenic River Forest Service Land State Public Lands Other State Lands Bureau of Land Management Lands National Park Service Lands Private; Local Government; Undesignated Sequoia Groves Wildfire Daily Perimeter
---	---	---	---

N

Miles

0 2 4

Kilometers

0 2 4

SUPPRESSION REPAIR