



# Talley RX Burn Survey Monumentation



- R-4, Stone  
Orange Carsonite  
X=538990  
Y=4212468
- R-5, Stone  
X=539384  
Y=4212470
- S-3, Stone  
Orange Carsonite  
X=538608.88  
Y=4212060.10  
Survey-Grade
- S3-4, FS Capped Rebar  
Alum Post  
X=538614.51  
Y=4211911.30  
Survey-Grade
- S-4, Stone  
PC Carsonite  
X=539000  
Y=4212057
- T-4, Stone  
PC Carsonite  
X=539006  
Y=4211650
- T-5, Stone  
X=539387  
Y=4211652
- U-4, Stone  
PC Carsonite  
X=539021  
Y=4211240
- U-4.5, Stone  
X=539212  
Y=4211240
- U-5, Stone  
PC Carsonite  
X=539402  
Y=4211240
- V-4, Stone  
PC Carsonite  
X=539028  
Y=4210815
- V-5, Stone  
PC Carsonite  
X=539413  
Y=4210823


Coordinates shown are approximate, unless noted as Survey-Grade  
PC Carsonite = Perry County records indicate a carsonite post present



**EXISTING SURVEYS**

Original Government Survey				Original Survey Evidence Found			
Year Surveyed:		By:		Date of Search:		By:	
Original Monument:				Monument Found:			
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance
<b>Subsequent Corner Restoration</b>				<b>Evidence of Subsequent Corner Restoration Found</b>			
Where Filed or Recorded:				Year Searched:	3/1/06	By:	B. Stone
Book:	Page:	Date:		Monument Found	6"x 7" stone with a + on top, leaning to the south and standing 11" above the ground. Scribbled on the south side: R-R 3		
Monument Set:				Species	Diameter	Bearing	Distance


**OTHER EVIDENCE**

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
<p>The stone is located on a south slope approximately 150 feet south of the knob on a break in the slope. The top of the knob which appears on the 1999 aerial photos as an old open area is covered with brush.</p> <p>The bottom of the slope is approximately 120 feet south.</p> <p>The head of the drainage can be seen S 62°W approximately 300 feet.</p> <p>The gravel road on the ridgetop is west approximately 350 feet.</p> <p>An orange Perry County carsonite surveyors post is standing on the east side of the stone and can be seen from the road.</p>	

**PERPETUATION RECORD**

Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position.



Corner Diagram	Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.									
	<p><b>Bearing Trees without tags:</b></p> <table> <tr> <td><b>T. Poplar</b></td> <td><b>B. Walnut</b></td> </tr> <tr> <td>20"</td> <td>8"</td> </tr> <tr> <td>N 33°E</td> <td>S 27°E</td> </tr> <tr> <td>12.2 Ft.</td> <td>8.2 Ft.</td> </tr> </table>		<b>T. Poplar</b>	<b>B. Walnut</b>	20"	8"	N 33°E	S 27°E	12.2 Ft.	8.2 Ft.
<b>T. Poplar</b>	<b>B. Walnut</b>									
20"	8"									
N 33°E	S 27°E									
12.2 Ft.	8.2 Ft.									
	Corner Recordation:	Certificate Prepared:								
	Filed and Recorded in County records:	Date:								
	Book:	Page:								
<b>Section: 30</b>	<b>Geodetic Coordinates:</b>	Lat./N.   Long./E.								
	Edited By: <b>Robert J. Stone</b>	Date Created: <b>4/6/06</b>								


**EXISTING SURVEYS**

**Original Government Survey**



**Original Survey Evidence Found**

Year Surveyed:	<b>1805</b>	By:	<b>E. Buckingham</b>	Date of Search:		By:	
Original Monument:	<b>Wooden Post</b>			Monument Found:			
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance
<b>Elm</b>	<b>14"</b>	<b>N 10°E</b>	<b>31 Lks.</b>				
<b>W. Oak</b>	<b>16"</b>	<b>S 82°W</b>	<b>24 Lks.</b>				
<b>Subsequent Corner Restoration</b>				<b>Evidence of Subsequent Corner Restoration Found</b>			
Where Filed or Recorded:	<b>Perry County Recorders Office</b>			Year Searched:	<b>3/1/06</b>	By:	<b>B. Stone</b>
Book: <b>C</b>	Page: <b>121</b>	Date: <b>9/28/1874</b>		Monument Found	<b>10" x 11" stone with a + on top, 2" above the ground and scribed on the south side: R-R 4 19 20 29 30</b>		
Monument Set:	<b>Stone</b>						
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance
<b>W. Oak</b>	<b>16"</b>	<b>S 82°W</b>	<b>24 Lks.</b>				
<b>W. Oak</b>	<b>12"</b>	<b>N 75°E</b>	<b>21 Lks.</b>				
<b>W. Oak</b>	<b>15"</b>	<b>S 12°W</b>	<b>23 Lks.</b>				

**OTHER EVIDENCE**

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
<p>The stone is located approximately down 1/3 of the north slope and on the uphill side of a bench in the slope.                  It has previously been painted orange and sits in a small depression.                  A 40" tall 9" diameter burnt stump with old north – south oriented barbwire is N 63°E 12.4 feet.                  Timber is sapling size in all directions.</p>	


**PERPETUATION RECORD**

Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position.	
	
<b>Corner Diagram</b>	Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.
	<b>Bearing Trees without tags:</b>
	<b>W. Oak (with old barbwire wrapped around) 11" N 68°W 4.0 Ft.</b>
Corner Recordation:	Certificate Prepared:
Filed and Recorded in County records:	Date:
Book:	Page:
Section: <b>30</b>	Geodetic Coordinates: Lat./N. Long./E.
Edited By: <b>Robert J. Stone</b>	Date Created: <b>3/9/06</b>




**EXISTING SURVEYS**

Original Government Survey				Original Survey Evidence Found			
Year Surveyed:		By:		Date of Search:		By:	
Original Monument:				Monument Found:			
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance
Subsequent Corner Restoration				Evidence of Subsequent Corner Restoration Found			
Where Filed or Recorded:				Year Searched:	<b>12/03/04</b>	By:	<b>B.Stone</b>
Book:	Page:	Date:		Monument Found	<b>3" x 7" stone with a deep + on top, heavily leaning west(downhill) and scribed 2 on south side. Pieces have split off on the west side.</b>		
Monument Set:							
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance

**OTHER EVIDENCE**

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
<p><b>The stone is located on a steep west slope, 80 feet northwest (downhill) from an old entrenched roadbed on the ridgetop.</b></p> <p><b>An old broken metal gate with a roadmound is approximately 160 feet south.</b></p> <p><b>An orange carsonite Perry County Surveyor marker post stands at the northwest corner of the stone.</b></p> <p><b>Timber on private lands southwest and west of the old roadbed has been cut recently.</b></p> <p><b>Old barbwire fence remnants runs north and south</b></p>	

**PERPETUATION RECORD**

Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position.			
			
<b>Corner Diagram</b>		Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.	
		<p><b>There are no tags or other markings on these trees:</b></p> <p><b>W. Oak</b>  <b>18"</b>  <b>N 61°E</b>  <b>8.6 Ft.</b></p> <p><b>Maple ( with orange paint and old 10" barbwire)</b>  <b>S 11°W</b>  <b>11 Ft.</b></p>	
Corner Recordation:		Certificate Prepared:	
Filed and Recorded in County records:		Date:	
Book:		Page:	
<b>Section: 30</b>		<b>Indiana State Plane Coordinates 1983: N. 1022895.299 E. 3103456.873</b>	
Edited By: <b>Robert J. Stone</b>		Date Created: <b>12/08/04</b>	

LAND CORNER RECORD  
(RECTANGULAR SURVEY)

Index No. S-3


Perry Co. No. S-2

T 5 S R 1 W 2nd Mer. N.F. Hoosier County Perry State Indiana

CN 1/16 Corner common to section 30 and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed <u>1805</u> Original monument <u>None</u> <small>(wood post, stone, pile of stones, etc.)</small>	Year of search <u>N/A</u> By _____ Monument found _____
Bearing Trees Species _____ Diameter _____ Bearing _____ Distance _____	Original Bearing Trees Found Species _____ Diameter _____ Bearing _____ Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed <u>N/A</u> By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc...)</small>	Year of search <u>2006</u> By <u>VHM</u> <u>Recovered sandstone solid in ground with hieroglyphics on South face and "+" on top</u>
Bearing Trees, Reference Objects Species _____ Diameter _____ Bearing _____ Distance _____	



Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record Distance \_\_\_\_\_  
 Measured Distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc... Cite source of testimony, if any. Situated in hardwoods on a Northwesterly down slope 10 feet Southeast of a steep drop. Approximately 100 feet± North and 70 feet± West of a Northeast/Southwest Forest Service Trail.

Perpetuation Record

Monument and accessories established. Include brief description of area. Stone is weathering/deteriorating and left as recovered.

W. Oak	W. Oak	W. Oak	Carsonite Post
13"	19"	12"	
N 22° W	N 56° E	S 53° E	North
11.2'	8.2'	14.3'	0.5'
Tagged	Unmarked	Tagged	
& Scribed		& Scribed	
W/wire			

At time of search:

- Did you have the record description? Yes X No \_\_\_\_\_
- How was search area located? Surveying
- Man hours spent in search 2
- Do you think additional search might recover evidence? Yes \_\_\_\_\_ No X
- Signature Vick H. M.

Certified corner restoration certificate prepared Yes \_\_\_\_\_ No X  
 Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County No. \_\_\_\_\_  
 Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

LAND CORNER RECORD  
(RECTANGULAR SURVEY)


Index No. ~~343~~ 53-.4


Perry Co. No. \_\_\_\_\_

T. 5 S. R. 1 W. 2nd Mer. N.F. Hoosier County Perry State Indiana

Property Corner \_\_\_\_\_ in Section 30 and \_\_\_\_\_

EXISTING SURVEYS

Original Government Survey	Original Evidence Found
Year surveyed <u>1805</u> Original monument <u>None</u> <small>(wood post, stone, pile of stones, etc.)</small>	Year of search <u>N/A</u> By _____ Monument found _____
<p style="text-align: center;">Bearing Trees</p> Species _____ Diameter _____ Bearing _____ Distance _____	<p style="text-align: center;">Original Bearing Trees Found</p> Species _____ Diameter _____ Bearing _____ Distance _____
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Year surveyed _____ By _____ Where filed or recorded _____ Monument _____ <small>(Original, concrete post, iron rod, etc...)</small>	Year of search _____ By _____
<p style="text-align: center;">Bearing Trees, Reference Objects</p> Species _____ Diameter _____ Bearing _____ Distance _____	



Relation of Evidence to Record Features Along Section Lines

Section line to sections \_\_\_\_\_  
 Object \_\_\_\_\_  
 Record Distance \_\_\_\_\_  
 Measured Distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc... Cite source of testimony, if any. Situated on South facing slope on East rim of small ridge, 300 feet East and 300 feet South of woods road running Northeast-Southwest, hardwoods all around with recent logging to Northwest.

Perpetuation Record

Monument and accessories established. Include brief description of area. Set 3/4" by 30" rebar with 3/4" aluminum cap, stamped as depicted, flush with ground. Placed a cairn of rocks around monument.

W. Oak	W. Oak	Ash	Alum. Witness
12"	14"	12"	Post
S 50° W	N 4° W	N 36° E	Southeast
27.7'	22.1'	11.0'	0.5'
Tagged	Tagged	Tagged	
& Scribed	& Scribed	& Scribed	

- At time of search:
- Did you have the record description? Yes X No \_\_\_\_\_
  - How was search area located? pacing, chaining, photo, maps, etc. SURVEYING
  - Man hours spent in search 2
  - Do you think additional search might recover evidence? Yes \_\_\_\_\_ No X
  - Signature Vick H. Ma

Certified corner restoration certificate prepared Yes \_\_\_\_\_ No X  
 Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County No. \_\_\_\_\_  
 Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_

Index No V-5 LAND CORNER RECORD FSM 7150  
 T. 5S R. 1W 2nd P.Mer. County Perry State of Indiana  
 Sec. Corner common to Sections 29, 30, 31, 32 Hoosier National Forest

EXISTING SURVEYS

Original Government Survey  
 Year Surveyed 1805 By \_\_\_\_\_  
 Original Monument Wood Post  
 Species Dia Bearing Dist  
 BT's W. Oak 14" S87E 25.0ft  
B. Oak 10" S82W 26.0ft

Original Survey evidence Found  
 Date of Search 1-1993 By KENCO-AMTECH  
 Monument Found Wood Post (Not Found)  
 Orig. Species Dia Bearing Dist  
 BT's Not Found  
 Found \_\_\_\_\_

Subsequent Corner Restoration  
 Date Surveyed \_\_\_\_\_ By Co. Survey  
 Where Filed or recorded: Perry  
 Book: B Page 56 Perry County  
Recorders off.

Monument Set Stone  
 BT's Species Dia Bearing Dist  
 Ref. B. Oak 11" S26 1/2 E 37.0ft  
 Obj. B. Oak 10" N64E 37.0ft

Evidence of Subsequent Corner Restoration Found  
 Date of Search 1-1993 By KENCO-AMTECH  
 Monument Found Stone 4" x 6" with T on

Top Protruding 4" & Leaning South, with  
VV 4 scribed on South Side, Firmly  
Set in ground & Roots of 26" W. Oak & 4" Hickory  
 Species Dia Bearing Dist  
 BT's Original BTs Not Found  
 Found \_\_\_\_\_

Subsequent Corner Restoration  
 Date Surveyed 1982 By USFS  
 Where Filed or recorded: T. City  
 Book: \_\_\_\_\_ Page \_\_\_\_\_ Forest Service  
Corner Card

Monument Set Stone MKD. VV 4  
 BT's Species Dia Bearing Dist  
 Ref. W. Oak 24" N45E 2.0ft  
 Obj. W. Oak 11" N66W 25.0ft


Evidence of Subsequent Corner Restoration Found  
 Date of Search 1-1993 By KENCO-AMTECH  
 Monument Found Stone (see Above)

	Species	Dia	Bearing	Dist
BT's	<u>W. Oak</u>	<u>26"</u>	<u>N45E</u>	<u>2.1ft.</u>
Found	<u>W. Oak</u>	<u>12"</u>	<u>N66W</u>	<u>25.2ft.</u>

OTHER EVIDENCE

Describe corner location relative to nearby features and how to reach the corner location - note fences roads, timber, streams, topo changes, etc: Stone is located on slight southerly slope, 265 ft ± North of an old road bed and the Main Hollow Drain running westerly, thick cedar timber to the south and larger hardwood to the N. Some remnant of barbed wire fence Wly & Sly. STONE leans Sly.

Sketch of Monument



PERPETUATION RECORD

Monument: Describe new monument set, or work done to preserve existing monument. Stone was left as found, set Carsonite sign post 1ft south of stone.

Accessories: Describe new Bt's and/or witness objects established or work done to preserve existing evidence  
12" & 26" W. Oak have tree tags and grown over BT Blazes (left in place)  
1/2" rebar set with plastic cap marked traverse point KAI, between old road & main drain at S32-22W 283.17' from Stone

CORNER DIAGRAM




Photo Identified \_\_\_\_\_  
 Photo # \_\_\_\_\_  
 Strip/Series \_\_\_\_\_  
 Pinpricked \_\_\_\_\_  
 Search Hours 2 1/2

Corner Recordation Yes \_\_\_\_\_  
 Certificate prepared: No \_\_\_\_\_  
 Filed or recorded in County \_\_\_\_\_  
 Records: Date: \_\_\_\_\_  
 Book: \_\_\_\_\_ Page: \_\_\_\_\_

Corner Record by: Ed Fleener Date: 3-30-93