



Requires PDF Maps

R. 27 W

R. 26 W

R. 25 W

R. 24 W

R. 23 W

T. 23 N

T. 22 N

T. 23 N

T. 22 N

T. 21 N

R. 27 W

R. 26 W

R. 25 W

R. 24 W

R. 23 W

Southern Tier Flood 2017
MO-MTF-170313




Assessment Map Roads & Recreation Sites

May 12, 2017 0700

Branch One
Division Zone 3
Cassville Ranger District
Mark Twain National Forest

Data Current as of 5/11/2017 @ 1530

**FS Roads, Zone 3 - Cassville RD
Needing Assessment = 12.6 Miles**

OPERATIONAL MAINTENANCE LEVEL
3 - Suitable for Passenger Cars - 11.1 Miles
4 - Moderate Degree of User Comfort - 1.5 Miles

**FS Recreation Sites, Zone 3 - Cassville RD
Needing Assessment = 7 sites**

SITE TYPES
Day Use Area - 4
Observation Site - 1
Trailhead - 2

Assessment Layers

Road Assessment

- Impassable - 0 miles
- Passable with Damage - 17.8 miles
- No damage - 4.0 miles
- Unreported - 12.6 miles

Rec Site Assessment

- Unreported - all sites
- Open/minor damage
- Closed/significant damage

Legend


OPER_MAJNT_LEVEL

- 1 - BASIC CUSTODIAL CARE (CLOSED)
- 2 - HIGH CLEARANCE VEHICLES
- 3/4 - SUITABLE FOR PASSENGER CARS


- Campground (1)
- Trailhead (2)
- Observation Site (1)
- Day Use Area (4)
- Non-Motorized Trail
- Gate

- Missouri Numbered Routes
- Missouri Lettered Route
- County Road
- Other Roads
- Private Road
- Railroad

- Mark Twain National Forest
- Channel in Water Area
- Stream - Intermittent
- Stream - Perennial
- Pit
- Quarry or Open Pit Mine
- Sand Area
- Land Subject to Inundation
- Open Water - Perennial
- Open Water - Intermittent
- Flood Hazard
- USDA FOREST SERVICE



1:63,360



1 inch = 1 miles
Contour Interval 20-Ft.

NAD 1983 Datum
UTM 15 North

