

BRIDGER FOOTHILLS MT-CGF-000214

Structure Assessment 9/11/20

Perimeter as of 9/7/20 @ 2100 8,224 ac.




Datum NAD83 0 0.125 0.25 0.5 0.75 1 Miles

JRA 9/11/20 1846

Structures

Primary Structure Damage

- Destroyed
- Major
- Minor
- No Damage



45°47'N 45°46'N 45°45'N 45°44'N 45°43'N 45°42'N 45°41'N 45°40'N