

BRIDGER FOOTHILLS MT-CGF-000214



Structure Assessment 9/11/20

Perimeter as of 9/7/20 @ 2100 8,244 ac.

0 0.1 0.2 0.4 Miles



9/11/2020 1347

PAGE 4

Structures

Structure Damage

- Destroyed
- Major
- Minor
- No Damage

