


SUPPRESSION REPAIR




Granite Pass Complex

MT-LNF-000962
8/26/2021 Day

5910 acres
IR updated 8/16/21 @ 03:26

Other	Access or Improved Road	Dip Site	Closure	Repair Point	Restricted Water Source	Repair Needed
Wildfire Daily Fire Perimeter	Other	Helispot	Lookout	Landing or Log Deck	Paved FS Road	Unknown
Completed Dozer Line	Repair Line	Helibase	Other	Culvert	Gravel Road	Completed - Inspected
Completed Fuel Break	Road Repair	Division Break	Mark	Mobile Weather Unit	Dirt Road	In Progress
Completed Hand Line	MT/ID State Boundary	Water Development or Draft Site	Water Source	Repeater	Unimproved Road	Repair Needed
Completed Mixed Construction Line	Proposed Great Burn Wilderness Area	Stream Crossing	Drop Point	Water Source	Unimproved Road	Unknown
Completed Road as Line	FS Wilderness Boundary	Road Repair				



0 0.5 1 2 Miles