


SUPPRESSION REPAIR



Granite Pass Complex

MT-LNF-000962

8/20/2021

5910 acres

IR updated 8/16/21 @ 03:26

- Other
- Wildfire Daily Fire Perimeter
- Completed Dozer Line
- Repair Line
- MT/ID State Boundary
- Completed Fuel Break
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Road as Line
- Access or Improved Road

- Fence
- Other
- Unimproved Landing Area
- Division Break
- Incident Command Post
- Drop Point
- Closure
- Value at Risk
- Other
- Landmark
- Water Development or Draft Site
- Stream Crossing
- Repair Point
- Landing or Log Deck

- Helispot
- Helibase
- Unimproved Landing Area
- Division Break
- Incident Command Post
- Drop Point
- Closure
- Lookout
- Mobile Weather Unit
- Internet Access
- Repeater
- Water Source
- Restricted Water Source
- Mile Marker

- Culvert
- Gravel Road
- Dirt Road
- Unimproved Road
- No Repair Needed
- Completed - Inspected
- In Progress
- Repair Needed
- No Repair Needed
- Unknown
- Completed - Inspected
- In Progress

