




Category	Length (miles)
Completed Dozer Line, Completed - Ready for Inspection	1.00
Completed Dozer Line, Completed - Inspected	3.21
Completed Dozer Line, In Use - Fire Management	3.48
Completed Dozer Line, Needs Assessment	0.21
Completed Dozer Line, Repair Needed	26.47
Completed Fuel Break, Completed - Ready for Inspection	0.00
Completed Fuel Break, Completed - Inspected	0.00
Completed Fuel Break, Completed - Needs Assessment	0.00
Completed Fuel Break, Repair Needed	0.04
Completed Hand Line, Completed - Ready for Inspection	0.76
Completed Hand Line, Completed - Inspected	1.79
Completed Hand Line, In Use - Fire Management	0.28
Completed Hand Line, Needs Assessment	0.00
Completed Hand Line, Repair Needed	11.09
Completed Mixed Construction, Completed - Ready for Inspection	0.18
Completed Mixed Construction, Completed - Inspected	0.14
Completed Mixed Construction, In Use - Fire Management	1.10
Completed Mixed Construction, Needs Assessment	0.00
Completed Mixed Construction, Repair Needed	17.55
Completed Road as Line, Completed - Ready for Inspection	4.51
Completed Road as Line, Completed Inspected	1.20
Completed Road as Line, In Use - Fire Management	1.64
Completed Road as Line, Needs Assessment	1.33
Completed Road as Line, Repair Needed	32.94
Access Route, Completed - Ready for Inspection	0.00
Access Route, Completed - Inspected	0.00
Access Route, In Use - Fire Management	10.81
Access Route, Needs Assessment	0.16
Access Route, Repair Needed	28.56

Event Point - Repair Status

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- Other - See Comments

Event Line - Repair Status

- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Repair Deferred
- Other - See Comments

- Division Break
- Hazard
- Helispot
- Sling Site
- Lookout
- Medical
- Drop Point
- Closure


- Staging Area
- Fence - Cut/Damaged
- Draft Site
- Mobile Weather Unit
- Internet Access
- Repeater
- Value at Risk
- Other

- Landmark
- Gate
- Bridge
- Stream Crossing
- Road Repair
- Resource Location
- Repair Point
- Landing or Log Deck

- Slash Pile
- Culvert
- Clean Up Area
- Other Property
- Pump
- Water Tank

- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Plow Line
- Completed Road as Line
- Access Route
- Fence

- Other
- Repair Line
- Road Repair
- Wildfire Perimeter



0 0.25 0.5 Miles

1:33,603 CAT
IR Flown on 9/17/2025 at 2305 MDT. Aircraft Sensor: N115Z / Phoenix
NAD 1983 2011 Datum, Lat/Long Grid

