



**Whittier
Suppression Repair
CA-LBOR 001770
July 24, 2017**

Branch I

Branch II

- Highway
- Road - Light Duty - Dirt
- Road - Light Duty - Paved
- Road - Light Duty - Unspecified Composition
- Road - Unimproved
- - - - Trail
- Foot Trail



0 1 2 4 Miles

- | | | | |
|---|------------------------------|---|---------------------------|
| () Division | ⚠ Hazard Tree, Repair Needed | Ⓜ Other Large Dozer Push (parking area etc.), Repair Needed | — Repair Lines |
| Branch | 🛠 Road Repair, Repair Needed | Ⓞ Other, Repair Needed | — Natural Barrier |
| — Fixed Wing Retardant | 🚧 Culverts, Repair Needed | 🚧 Retardant Track or Point, Repair Needed | ⚡ Dozer Line |
| — Rotor Retardant | 🚧 Dozer Line, Repair Needed | 🚧 Sling Site, Repair Needed | ⚡ Dozer on Road |
| — Repair Points | 📍 Drop Point, Repair Needed | 📍 Staging Area, Repair Needed | H - H - H - Hand Line |
| 🌳 Downed Tree, Repair Needed | 📍 Equipment Found | 📍 Trails, Repair Needed | — Road Repair |
| 🌊 Stream Crossing, Repair Needed | 📍 Fence, Repair Needed | 📍 Water Development & Draft Site, Repair Needed | 🟡 Repair Needed |
| 🚧 Other Large Dozer Push, Stage 2 Repair Complete | 🚧 Gate, Repair Needed | 📍 Wildlife Habitat Concern | 🟠 Stage 1 Repair Complete |
| | 📍 Helispot, Repair Needed | | 🟢 Stage 2 Repair Complete |
| | | | 🟢 Repair Approved |

