

**Suppression Repair
Umpqua North Complex
Div E**
OR-UPF-000406
September 25, 2017

- Repair Status**
■ Completed - Inspected
■ Repair Needed
■ Needs Grading or District Maintenance
- Drop Point
 - ⊕ Unimproved Landing Area
 - ⊕ Helispot
 - ⊕ Repeater
 - ⊕ Staging Area
 - ⊕ Water Source
 - Fire Location - Smoke Check
 -) (Division Break
 - ◇ Melted Carsonite Rd Sign
 - ⊕ Log Decks
 - ▲ Slash Disposal Areas
 - ◆ Slash Piles
 - Dip Sites**
 - ⊕ Do Not Use
 - ⊕ Restricted
 - ⊕ OK
 - 100 ft Contours
 - xx xx Completed Dozer Line
 - Completed Hand Line
 - R · R Road as Completed Line
 - Escape Route
 - ⊕ Other
 - - - Proposed Handline
 - Bureau of Land Management
 - Private
 - United States Forest Service
 - Fire Area

