

**Suppression Repair
Umpqua North Complex
Div M/O**
OR-UPF-000406
September 25, 2017

Repair Status
■ Completed - Inspected
■ Repair Needed
■ Needs Grading
■ or District Maintenance

- Drop Point
- ⊕ Unimproved Landing Area
- ⊕ Helispot
- ⊕ Mobile Weather Unit
- ⊕ Repeater
- ⊕ Staging Area
- ⊕ Water Source
- ⊕ Value at Risk
- ⊕ Fire Location - Smoke Check

⎓ Division Break

- ◇ Melted Carsonite Rd Sign
- ⊕ Log Decks
- ▲ Slash Disposal Areas
- ⬢ Slash Piles

- Dip Sites**
- ⊕ Do Not Use
 - ⊕ Restricted
 - ⊕ OK

- 100 ft Contours
- ⊕ Completed Dozer Line
- Completed Hand Line
- ⊕ Road as Completed Line
- ⊕ Other
- ⊕ Proposed Handline
- ⊕ United States Forest Service
- ⊕ Fire Area

