


# Suppression Repair Umpqua North Complex Operations OR-UPF-000406 September 29, 2017



**Legend**

- ↑ Log Decks
- Helispot
- Drop Point
- Staging Area
- Camp
- Unimproved Landing Area
- ▢ Incident Command Post
- ▢ Mobile Weather Unit
- Repeater
- Water Source
- Restricted Water Source
- Value at Risk
- Slash Pile
- Division Break
- ▲ Slash Disposal Areas
- ◆ Melted Carsonite Rd Sign
- Do Not Use
- Restricted
- OK With Consult
- OK
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Escape Route
- Other
- Fire Area

**Dip Sites**

- Do Not Use
- Restricted
- OK With Consult
- OK

**Repair Status**

- Completed - Inspected
- Repair Needed
- Needs Grading of District Maintenance

**Scale:** 0 1 2 3 4 Miles

**North Arrow**

123°5'W 123°4'W 123°3'W 123°2'W 123°1'W 122°59'W 122°57'W 122°55'W 122°53'W 122°51'W 122°49'W 122°47'W 122°45'W 122°43'W 122°41'W 122°39'W 122°37'W 122°35'W 122°33'W 122°31'W 122°29'W 122°27'W 122°25'W 122°23'W 122°21'W 122°19'W 122°17'W