



**Suppression Repair  
Umpqua North Complex  
Div M/O**  
OR-UPF-000406

- Repair Status**  
█ Completed - Inspected  
█ Repair Needed  
█ Needs Grading or District Maintenance
- Drop Point
  - Ⓜ Unimproved Landing Area
  - Ⓜ Helispot
  - Ⓜ Mobile Weather Unit
  - Ⓜ Staging Area
  - Ⓜ Water Source
  - Ⓜ Value at Risk
  - Ⓜ Division Break
  - Ⓜ Melted Carsonite Rd Sign
  - Ⓜ Log Decks
  - Ⓜ Slash Disposal Areas
  - Ⓜ Slash Piles
- Dip Sites**
- Ⓜ Do Not Use
  - Ⓜ Restricted
  - Ⓜ OK
- 100 ft Contours
  - Ⓜ Completed Dozer Line
  - Completed Hand Line
  - Ⓜ Road as Completed Line
  - Ⓜ Other
  - Ⓜ Active Timber Sales
  - Ⓜ United States Forest Service
  - Ⓜ Fire Area



Miles 0 0.25 0.5

N