

**HENDRIX
OR-RSF-278
Repair Status Map**
Datum: North American 1983
07/25/2018
Day Shift
Perimeter as of: 07/25/18 @ 0152
Approx: 1,081 ac

FireLine Repair



- No Repair Needed
- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- ? Other - See Comments
- Unknown

FireLine Repair

- No Repair Needed
- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- ? Other - See Comments
- Unknown

- Division Break
- Camp
- Drop Point
- Helispot
- Pump
- Sling Site
- Water Source
- ▲ Value at Risk
- ◆ Road Washout

- Uncontrolled Fire Edge
- Completed Line
- Completed Dozer Line
- Completed Hand Line
- Road as Completed Line
- Line Break Completed
- Other



S. Bushnell
07/25/18
0901 Hours