


- █ Completed - Inspected
- █ In Progress
- █ Repair Needed
- █ Completed - Ready for Inspection
- █ Drainage
- █ Unknown
- █ No Repair Needed



Spencer
Repair Status Map
 PNL0W5 (1502)
 September 19, 2018

