



- Road
- Hedgehog
- 4x4 Vehicle Access
- Trail
- Transmission Lines
- Bureau of Land Management
- U.S. Forest Service
- State
- Private/Unknown
- Drop Point
- Fireline Location
- M Wilderness
- Truck Turnout
- Division Break

**Suppression Repair Map NORTH**  
**NORTH KLAMATHON INCIDENT**  
 OR-MED-268

Miles

0      0.225      0.45      0.9

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- Unknown
- No Repair Needed

North Klamathon  
 Suppression Repair  
 PNLYL8 (1502)  
 OR-MED-268  
 Sept. 15, 2018  
 NAD83  
 1:10,360