



Completed	14
Needs Repair	8
Unknown	26




- ★ City
- Ⓜ Incident Command Post
- Ⓜ Helibases

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress

- Repair Needed
- Unknown
- No Repair Needed

Wagner Complex Suppression Repair Map

Southern Oregon



S OR
MED RSF
Repair
Sep 20, 2018

Created by:
Southwest Oregon GIS Support
9/19/2018 10:42 PT