


- Trail
- Drop Point
- Helipad
- 4x4 Vehicle Access
- Division Break
- Private Land
- Wilderness Location
- U.S. Forest Service
- State
- Private/Unknown
- Truck Turnaround

Suppression Repair Map NORTH
NORTH KLAMATHON INCIDENT
 OR-MED-268



- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- Unknown
- No Repair Needed

North Klamathon
 Suppression Repair
 PNLYL8 (1502)
 OR-MED-268
 Sept. 22, 2018
 NAD83
 1:10,360