




Completed	26
Needs Repair	6
UTL	6
Unknown	11



- ★ City
- Incident Command Post
- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- Unknown
- No Repair Needed
- Other - See Comments

# Wagner Complex Suppression Repair Map

## Southern Oregon



S OR  
MED RSF  
**Repair**  
Sep 22, 2018

Created by:  
Southwest Oregon GIS Support  
9/22/2018 11:31 PT