


- Completed - Inspected
 —— In Progress
—— Repair Needed
- Completed - Ready for Inspection
 —— Drainage
● Unknown
- No Repair Needed



Spencer
Repair Status Map
 PNL0W5 (1502)
 September 28, 2018

