



- █ Completed - Inspected
- █ In Progress
- █ Repair Needed
- █ Completed - Ready for Inspection
- █ Drainage
- █ Unknown
- █ No Repair Needed

**Snowshoe**  
**Repair Status Map**  
 PNL0ZN (0615)  
 September 28, 2018

Miles