


DIV T

4x4 Vehicle Access Only
East of Marker


H-3

H-2



- Road
- Drop Point
- Trail
- Transmission Lines
- Bureau of Land Management
- U.S. Forest Service
- State
- Private/Unknown
- Division Break
- Feltaria Locations
- M Wilderness
- Truck Turnout

Suppression Repair Map WEST
NORTH KLAMATHON INCIDENT
OR-MED-268



- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- Unknown
- No Repair Needed

North Klamathon
Suppression Repair
PNLYL8 (1502)
OR-MED-268
Sept. 30, 2018
NAD83
1:11,320