


- Completed - Inspected
 —— In Progress
—— Repair Needed
- Completed - Ready for Inspection
 —— Drainage
—— Unknown
- No Repair Needed



**Spencer**  
**Repair Status Map**  
 PNL0W5 (1502)  
 September 30, 2018

