



<p>Suppression Repair East Klondike / Taylor Creek</p> <p>Chrome Ridge Area, Taylor/Klondike East</p> <p>Oct 5, 2018</p> <p>Klondike Fire OR-RSF-000354 P6L00P (0610)</p> <p>Taylor Creek Fire OR-MED-000395 PDL001 (1502)</p> <p>Southwest Oregon GIS Support</p>	<ul style="list-style-type: none"> ● Completed - Inspected ● Completed - Ready for Inspection ● In Progress ● Repair Needed ● No Repair Needed ● Other - See Comments ● Unknown ◆ TAPS ◆ Archaeological Site ◆ Bridge ◆ Camp ▲ Chipping Area ○ Culverts ● Drop Point E Equipment Found X Fence → Gates G Guzzler ■ Hazard Tree ◆ Hazmat Site D Helibase ● Helispot ■ Incident Command Post ● Large Down Woody Debris ■ Other ■ Other Large Down Push (parking area, etc.) ■ Retardant Track or Point X Retardant in Avoidance Area ■ Road Barrier ■ Road Repair ■ Road Sign ▲ Safety Zone ○ Spring S Staging Area ■ Stream Crossing ■ Structure Wrap ■ Trails ■ Trash ■ Uncomplicated / Low-Risk Saw Work ■ Water Development & Draft Site ■ Invasive Plants ■ Sensitive Plants --- Trails - - - - - Completed Dazzleline - - - - - Completed Handline - - - - - Road as Completed Line --- Access or Improved Road --- ZoneBreakLine 	<p>Created by: Southwest Oregon GIS Support 10/4/2018 23:22 PT</p> <p>Miles 0 0.25 0.5 1</p>
--	--	--