


**Watson Creek
OR_FWF_000360
Suppression Repair Status
September 6, 2018**



	<ul style="list-style-type: none"> Dip Site Drop Point Staging Area Water Source Helispot Hot Spot Other-Repair Point 	<ul style="list-style-type: none"> Road as Completed Line Dozer Control Line Dozer - Exterior Line FENCE 	<ul style="list-style-type: none"> Other 	<p>Repair Status Point</p> <ul style="list-style-type: none"> Completed - Inspected (11) Completed - Ready for Inspection (2) In Progress (2) Repair Needed (29) Unknown (4) 	<p>Repair Status Line</p> <ul style="list-style-type: none"> Completed - Inspected Completed - Ready for Inspection In Progress Repair Needed Unknown No Repair Needed 	<ul style="list-style-type: none"> READ feature point READ Approx. feature point 	<div style="text-align: right;"> <p>Datum NAD 83 NW IMT 6 9/5/2018 9:30:06 PM</p> </div>
--	---	--	--	---	---	--	--