



**Watson Creek**  
**OR\_FWF\_000360**  
**Suppression Repair Status**  
**September 6, 2018**  
**Southwest**



- |              |                |                      |                            |           |  |                                    |                              |
|--------------|----------------|----------------------|----------------------------|-----------|--|------------------------------------|------------------------------|
| ● Dip Site   | ● Helispot     | ● Other-Repair Point | --- Road as Completed Line | ○ Other   | <b>Repair Status Point</b>             | <b>Repair Status Line</b>          | ● READ feature point         |
| ● Drop Point | ● Staging Area |                      |                            | --- FENCE | ● Completed - Ready for Inspection (1) | ● Completed - Inspected            | ● READ Approx. feature point |
|              |                |                      |                            |           | ● Repair Needed (10)                   | ● Completed - Ready for Inspection |                              |
|              |                |                      |                            |           | ● Unknown (1)                          | ● In Progress                      |                              |
|              |                |                      |                            |           |  | ● No Repair Needed                 |                              |

