

Suppression Repair

Beachie Creek
ORWIF-200299
Beachie 7

Riverside
ORMHF-000859

10/06/20
Page: 14

- Repair Point Status**
- Repair Needed
 - Unknown
- Repair Line Status**
- Repair Needed
- Legend:**
- Contained Line
 - Road as Completed Line
 - Aerial Hazard
 - Uncontrolled Fire Edge
 - BPA Transmission Lines
 - Wildfire Daily Fire Perimeter
 - Culvert
 - ◆ Dip Site
 - ★ Hazard
 - ⚠ Lookout
 - Ⓜ Repeater
 - ⚠ Value at Risk
 - ⚠ Branch Break
 - Major road
 - Intermediate road
 - Minor road
 - Decommissioned or Closed
 - Rivers and Streams
 - Lake, Pond or Reservoir
 - County Boundary
 - Ranger District Boundaries
 - Forest Service Wilderness Area
 - Bureau of Land Management
 - U.S. Forest Service
 - State
 - Private/Unknown
 - ▲ Structures
 - ⛑ Campground
 - 🏠 Cabin
 - 🏠 Trailhead
 - 🏠 Picnic Area

FC Point Type	Repair Status	Repair Comments	Label
Culvert	Repair Needed		
Culvert	Repair Needed	BAER ALERT - FSR 2223, MP 4.32, remove and replace with 36" x 24" culvert.	
Hazard	Repair Needed	Scaling? Excavator?	
Lookout	Repair Needed		
Repeater	Unknown		CMD-8
Value at Risk	Repair Needed		Bagby Hot Springs
Value at Risk	Repair Needed		Bull of the Woods Lookout
Value at Risk	Unknown		Jawbone Flats

FC Line Type	Repair Status	Repair Comments	Length Feet
Road as Completed Line	Repair Needed	Road as Line Needed to be Added and Repaired	
Road as Completed Line	Repair Needed	Road as Line Needed to be Added and Repaired	
Road as Completed Line	Repair Needed	Road as Line Needed to be Added and Repaired	
Road as Completed Line	Repair Needed	Road as Line Needed to be Added and Repaired	
Road as Completed Line	Repair Needed	Road as Line Needed to be Added and Repaired	
Road as Completed Line	Repair Needed	Road as Line Needed to be Added and Repaired	
Other	Repair Needed	Cover with brush. Pull flagging	1046

