

Suppression Repair



Beachie Creek
ORWIF-200299
Riverside
ORMHF-000859
Riverside 7

10/09/20
Page: 7

- BPA Transmission Lines
- Minor road
- Decommissioned or Closed
- ▲ Structures
- ▲ Campground
- ▲ Trailhead
- State Highway
- Major road
- Intermediate road
- County Boundary
- Ranger District Boundaries
- Forest Service Wilderness Area
- Bureau of Land Management
- U.S. Forest Service
- Private/Unknown

FC Point Type	Repair Status	Repair Comments	Label
Drop Point	No Repair Needed		DP-111
Landing or Log Deck	Unknown		
Repeater	Repair Needed		CMD 8
Value at Risk	Unknown		

FC Line Type	Repair Status	Repair Comments	Length Feet
Road as Completed Line	Unknown		780
Road as Completed Line	Repair Needed	Chipper needed after fire-M. Debris on Sep 19, 2020. Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch.	11641
Road as Completed Line	Completed - Inspected	Chipping needed to clear ditches	464
Planned Fire Line	Unknown		17307
Planned Fire Line	Repair Needed	Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch.	17301
Planned Fire Line	Completed - Inspected	Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch.	257
Other	Unknown		479
Other	Unknown		493
Other	Unknown		519
Other	Unknown		598
Other	Unknown		813
Other	Unknown		827
Other	Unknown		1312
Access or Improved Road	Unknown		29
Access or Improved Road	Unknown		155
Access or Improved Road	Unknown		341
Access or Improved Road	Unknown		479
Access or Improved Road	Unknown		576
Access or Improved Road	Unknown		601
Access or Improved Road	Unknown		842
Access or Improved Road	Unknown		2043
Access or Improved Road	Unknown		6158
Access or Improved Road	Unknown		8554



1:33,000 - 10/8/2020 21:23
Acres from GIS
North American 1983 Datum, LatLong Grid

