

Suppression Repair

Beachie Creek
ORWF-200299
Riverside
ORMHF-000859
10/13/20
Page: 1

- City, Town, or Community
- No Repair Needed
- Other - See Comments
- Unknown
- Fire Station
- Ranger Station
- Visitor/Information Center
- Trailhead
- Picnic Area
- Label Point 2020_GISS_Edit
- State Highway
- County Road
- Major road
- Intermediate road
- Minor road
- Decommissioned or Closed
- County Boundary
- ▲ Structures
- ✕ Completed Dozer Line
- ✕ Completed Hand Line
- ✕ Road as Completed Line
- ✕ Access or Improved Road
- ✕ Line Break Completed
- ✕ Completed Plow Line
- ✕ Repair Line
- Other
- Completed - Inspected
- Repair Needed
- In Use - Fire Management
- Completed - Ready for Inspection
- Repair Needed
- Other - See Comments
- Unknown
- Wildfire Daily Fire Perimeter
- City Limits
- Ranger District Boundaries
- Forest Service Wilderness Area
- Bureau of Land Management
- U.S. Forest Service
- U.S. Fish and Wildlife Service
- State
- Local Government
- Private/Unknown

FC Point Type	Repair Status	Repair Comments	Label
Culvert	Repair Needed	Debris around culvert inlet - remove debris	DP-64
Drop Point	Completed - Inspected	Pulled back slash piled by culvert and sustained. Add native seed if needed. -Lyan 10-9-20	DP-11
Drop Point	No Repair Needed	No repairs. REAF BERNARDS	DP-13
Drop Point	No Repair Needed		DP-53
Drop Point	No Repair Needed		DP-52
Drop Point	No Repair Needed		DP-57
Drop Point	No Repair Needed		DP-61
Drop Point	No Repair Needed		DP-62
Drop Point	No Repair Needed		DP-65
Drop Point	Repair Needed		DP-35
Drop Point	Repair Needed		DP-30
Drop Point	Repair Needed		DP-50
Drop Point	Repair Needed	Spread out the slash pile next to boulders. Add native seed as necessary. -Lyan 10-9-20	DP-60
Drop Point	Repair Needed	Cover exposed soil with other slash or native seed. -Lyan 10-9-20	DP-63

FC Line Type	Repair Status	Repair Comments	Length Feet
Road as Completed Line	Unknown		70
Road as Completed Line	Unknown		96
Road as Completed Line	Unknown		103
Road as Completed Line	Unknown		117
Road as Completed Line	Unknown		182
Road as Completed Line	Unknown		233
Road as Completed Line	Unknown		234
Road as Completed Line	Unknown		273
Road as Completed Line	Unknown		282
Road as Completed Line	Unknown		303
Road as Completed Line	Unknown		347
Road as Completed Line	Unknown		367
Road as Completed Line	Unknown		378
Road as Completed Line	Unknown		402
Road as Completed Line	Unknown		424
Road as Completed Line	Unknown		464
Road as Completed Line	Unknown		475
Road as Completed Line	Unknown		547
Road as Completed Line	Unknown		554
Road as Completed Line	Unknown		611
Road as Completed Line	Unknown		621
Road as Completed Line	Unknown		698
Road as Completed Line	Unknown		843
Road as Completed Line	Unknown		850
Road as Completed Line	Unknown		851
Road as Completed Line	Unknown		907
Road as Completed Line	Unknown		1024
Road as Completed Line	Unknown		1101
Road as Completed Line	Unknown		1202
Road as Completed Line	Unknown		1212
Road as Completed Line	Unknown		1236
Road as Completed Line	Unknown		1293
Road as Completed Line	Unknown		1305
Road as Completed Line	Unknown		1396
Road as Completed Line	Unknown		1392
Road as Completed Line	Unknown		1580
Road as Completed Line	Unknown		1679
Road as Completed Line	Repair Needed		746
Road as Completed Line	Repair Needed		2059
Road as Completed Line	Repair Needed		2993
Road as Completed Line	Repair Needed		3122
Road as Completed Line	Other - See Comments		488
Road as Completed Line	Other - See Comments		538
Road as Completed Line	Completed - Inspected		892
Road as Completed Line	Completed - Inspected	10/11/2020/kel_rfc- Inspected complete. 10/16/2020/kelwell-4611 Excavator cleaned ditch along road completed. As excavator walks out it will need to knock down the small berm that will prevent water on road from entering ditch. REAF Kipwell 10/9/20	15868
Road as Completed Line	Completed - Inspected	10/11/2020/kel_rfc- Inspected complete. 10/16/2020/kelwell-4611 Excavator cleaned ditch along road completed. As excavator walks out it will need to knock down the small berm that will prevent water on road from entering ditch. Areas of ditch repair. Most of these exposed dirt areas drain into ditch release culverts. The risk of sediment entering live streams below road. Evaluate after rain event to determine if sediment traps needed over winter.	25710
Repair Line	Unknown	Water Bars installed	196
Repair Line	Unknown	Needs fence repair	217
Repair Line	Unknown	Repair complete. Remainder of shown dozer line is existing road	340
Repair Line	Unknown	Repaired by hand tools	354
Repair Line	Unknown	Water bars	436
Repair Line	Unknown	Repair complete	513
Repair Line	Unknown	Water bars	529
Repair Line	Unknown	Water bars placed	640
Repair Line	Unknown	Repair complete	730
Repair Line	Unknown	Repair complete	946

0 0.5 1 2 Miles

1:33,000 - 10/12/2020 2025
Acres from GIS
North American 1983 Datum, LatLong Grid

