


Suppression Repair

Beachie Creek
ORWIF-200299
Riverside
ORMHF-000859
10/13/20
Page: 7

	Division Break		Planned Fire Line
	Drop Point		Other
	Repeater		Completed - Inspected
	Repair Needed		In Progress
	No Repair Needed		Repair Needed
	Campground		Unknown
	Trailhead		Wildfire Daily Fire Perimeter
			Ranger District Boundaries
			Forest Service Wilderness Area
			Bureau of Land Management
			U.S. Forest Service
			Private/Unknown

FC Point Type	Repair Status	Repair Comments	Label
Drop Point	No Repair Needed		DP-111
Repeater	Repair Needed		CMD R-8

FC Line Type	Repair Status	Repair Comments	Length Feet
Road as Completed Line	Unknown		780
Road as Completed Line	Repair Needed	Chipper needed after fire-M. Donegala Sep 15, 2020. Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch.	6562
Road as Completed Line	Completed - Inspected	Chipping needed to clear ditches	11645
Planned Fire Line	Unknown		464
Planned Fire Line	Repair Needed	Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch.	17307
Planned Fire Line	Completed - Inspected	Equipment currently masticating (9/28). Crews may be needed to break up and spread highly concentrated material in the ditch.	17307
Other	Unknown		257
Other	Unknown		479
Other	Unknown		493
Other	Unknown		519
Other	Unknown		598
Other	Unknown		813
Other	Unknown		827
Other	Unknown		1312
Access or Improved Road	Unknown		29
Access or Improved Road	Unknown		155
Access or Improved Road	Unknown		341
Access or Improved Road	Unknown		479
Access or Improved Road	Unknown		576
Access or Improved Road	Unknown		601
Access or Improved Road	Unknown		842
Access or Improved Road	Unknown		2043
Access or Improved Road	Unknown		6158
Access or Improved Road	Unknown		8554



0 0.5 1 2 Miles

1:33,000 - 10/12/2020 2034
Acres from GIS
North American 1983 Datum, LatLong Grid

