

Repair Map

Patton Meadow ORFWF210419


August 23, 2021

August 23, 2021

ORFWF210419

Patton Meadow

Repair Map




Repair Status Point

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- Unknown
- No Repair Needed
- Other - See Comments
- In Use - Fire Management

Repair Status Line

- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- Unknown
- No Repair Needed
- Other - See Comments
- In Use - Fire Management



ODF Team 3 GIS
08/22/2021 2:144
Acres from IR & OSC

Fox Cpx: 9,771 acres at 08/21/21 @ 07:30 hrs
Patton Meadow: 8,948 acres
Willow Valley: 824 acres

Fire Area	Road Repair	Division Break	Other	Oregon Parks and Recreation Department
Completed Burnout	Retardant Drop	Drop Point	Repair Point	US Forest Service
Completed Dozer Line	Fire Edge	Closure	Fence - Cut/Damaged	State Boundary
Completed Hand Line	Contained Line	Camp	Dozer Push	Buried Transmission Line
Completed Road as Line	Dip Site	Staging Area	Water Source	
Access or Improved Road	Helispot	Value at Risk	Structures	



Scan to download maps
Use the camera on a mobile device