Div T

Div H

Div W

Div D

DP-20
DP-21
DP-22
POW Dip
DP-23
Alder Ridge
H-11
DP-19
H-71
IRAWS 25
CMD-3
Clearwater Pond
H-19
H-16
DP-1
H-10
DP-6
H-13
IRAWS 26
CMD-4
DP-62
H-7
DP-60
H-6
H-4
DP-55
DP-31
DP-32
DP-53
DP-50
DP-35
Case Dip
Huber Dip
Big Butte Lookout
CMD-11
CMD-2
Asotin
LOWER GRANITE LAKE
TUCANNON FISH HATCHERY
LYONS FERRY FISH HATCHERY
UMATILLA NATIONAL FOREST
WENAHA-TUCANNON WILDERNESS
Peola Rd
Asotin Creek Rd
Charley Creek Rd
Cloverland Rd
Back Rd
Meyers Ridge Rd
Smoothing Iron Rd
Lookout Rd
Leuthe Rd
Knott Rd
Patawa Spur Rd
Fazzaral Rd
Knotgrass Ridge Rd
Mountain Rd
Diamond Creek Rd
Mill Rd
Sangster Rd
Onstot Rd
Savage Rd
Bennett Ridge Rd
West Mountain Rd
East Mountain Rd
Montgomery Ridge Rd
Harbin Grade Rd
Wenaha Ridge Rd
Whitetail Butte 3,537
Tamarack Butte 3,766
Little Butte 4,570
Big Butte 5,010
Potter Butte 4,472
Mount Misery 6,368
Diamond Peak 6,348
Cabin Saddle 5,485
Mount Horrible 5,817
Little Saddle 5,381
Halsey Butte 5,325
Bald Butte 5,459
Saddle Butte 5,860
Twin Buttes 5,656
Maloney Mountain 4,652
Rocky Butte 5,010
Tatone Butte 4,892
Willow Spring Saddle 4,516
Potter Hill 4,412
Goat Mountain 4,619
Tatman Mountain 3,563
Calloway Hill 3,707
Lost Point 5,016
Elk Point 5,256
Bear Wallow 5,377
Rocksberry Butte 5,328
Featham Butte 728
Twin Sisters 3,564
Oregon Butte 6,387
West Butte 6,263
Asotin
ASOTIN
CLARKSTON HEIGHTS-VINEYARD-WEST CLARKSTON-HIGHLAND
LEWISTON
HELLS GATE STATE PARK
Snake River Ave
Tammany Creek Rd
Scenic Hills Dr
Critchfield Rd
Southport Ave
Orchard Rd
Peola Rd
Asotin Creek Rd
Cloverland Rd
Back Rd
Meyers Ridge Rd
Smoothing Iron Rd
Lookout Rd
Leuthe Rd
Knott Rd
Patawa Spur Rd
Fazzaral Rd
Knotgrass Ridge Rd
Mountain Rd
Diamond Creek Rd
Mill Rd
Sangster Rd
Onstot Rd
Savage Rd
Bennett Ridge Rd
West Mountain Rd
East Mountain Rd
Montgomery Ridge Rd
Harbin Grade Rd
Wenaha Ridge Rd
Whitetail Butte 3,537
Tamarack Butte 3,766
Little Butte 4,570
Big Butte 5,010
Potter Butte 4,472
Mount Misery 6,368
Diamond Peak 6,348
Cabin Saddle 5,485
Mount Horrible 5,817
Little Saddle 5,381
Halsey Butte 5,325
Bald Butte 5,459
Saddle Butte 5,860
Twin Buttes 5,656
Maloney Mountain 4,652
Rocky Butte 5,010
Tatone Butte 4,892
Willow Spring Saddle 4,516
Potter Hill 4,412
Goat Mountain 4,619
Tatman Mountain 3,563
Calloway Hill 3,707
Lost Point 5,016
Elk Point 5,256
Bear Wallow 5,377
Rocksberry Butte 5,328
Featham Butte 728
Twin Sisters 3,564
Oregon Butte 6,387
West Butte 6,263
Asotin
ASOTIN
CLARKSTON HEIGHTS-VINEYARD-WEST CLARKSTON-HIGHLAND
LEWISTON
HELLS GATE STATE PARK
Snake River Ave
Tammany Creek Rd
Scenic Hills Dr
Critchfield Rd
Southport Ave
Orchard Rd
Peola Rd
Asotin Creek Rd
Cloverland Rd
Back Rd
Meyers Ridge Rd
Smoothing Iron Rd
Lookout Rd
Leuthe Rd
Knott Rd
Patawa Spur Rd
Fazzaral Rd
Knotgrass Ridge Rd
Mountain Rd
Diamond Creek Rd
Mill Rd
Sangster Rd
Onstot Rd
Savage Rd
Bennett Ridge Rd
West Mountain Rd
East Mountain Rd
Montgomery Ridge Rd
Harbin Grade Rd
Wenaha Ridge Rd

Prepared by CRMT12 7/29/2021 2153

Other Property
Pump
Water Tank
Airstrip or Airport
Dip Site
Helispot
Division Break
Drop Point
Staging Area
Lookout
Hot Spot - Spot Fire
Value at Risk
Other
Gate

Structure Wrap
Stream Crossing
Road Repair
Repair Point
Landing or Log Deck
Fence - Cut/Damaged
Dozer Push
Culvert
Clean Up Area
Mobile Weather Unit
Repeater
Water Source
Completed Dozer Line
Completed Hand Line

Completed Mixed Construction Line
Completed Road as Line
Planned Dozer Line
Planned Road as Line
Access or Improved Road
Fence
Fire Edge
Contained Line
Wildfire Daily Fire Perimeter
USFS Road Closures
Dry Gulch READ Sensitive Areas
Aerial Fire Avoidance
State Public Lands
Other State Lands

U.S. Fish & Wildlife Service Lands
Bureau of Land Management Lands
Private; Local Government; Undesignated
Forest Service Land

Repair Status Point
Completed - Inspected
In Use - Fire Management
Completed - Ready for Inspection
In Progress
Repair Needed
No Repair Needed
Other - See Comments
Unknown

Repair Status Line
Completed - Inspected
In Use - Fire Management
Completed - Ready for Inspection
In Progress
Repair Needed
No Repair Needed
Other - See Comments
Unknown

ATU Retardant Drops
Drop Lines: Last 14 days
Drop Points: Last 14 days
Drop Lines: Last 14 days
Retardant drop data is a live service from ATU

SUPPRESSION REPAIR

Lick Creek

OR-UMF-000658

7/30/21

CALIFORNIA FIRE INCIDENT MANAGEMENT TEAM 12
"Adapt...Improvise...and Overcome"

0 1 2 4 Miles

1:48,000 NAD83 UTM 11N

Lick Creek
OR-UMF-000658
REPAIR
7/30/21