

# Repair Div A

Schneider Springs  
WA-OWF-000453  
9/30/2021

107,118 acres at 9/27/2021 0700



- Dip Site
- Helispot
- Division Break
- Drop Point
- Closure
- Staging Area
- Lookout
- Value at Risk
- Other
- Landmark
- Bridge
- Stream Wrap
- Road Crossing
- Road Repair
- Resource Location
- Repair Point
- Landing or Log Deck
- Hazard Tree
- Dozer Push
- Mobile Weather Unit
- Repeater
- Hazard
- Water Source
- Restricted Water Source
- Completed Dozer Line
- Completed Fuel Break
- Completed Hand Line
- Completed Mixed Construction Line
- Completed Flow Line
- Completed Road as Line
- Access or Improved Road
- Road Repair
- Resource Location
- Repair Point
- Landing or Log Deck
- Hazard Tree
- Dozer Push
- FS - High Clearance/Closed
- State/Private Roads
- Wildfire Daily Fire Perimeter
- Administrative FS Boundary
- Federal Wilderness Boundary
- Resource Concern
- Whitebark Pine Polygons
- Whitebark Pine Trees
- Seed Trees
- African Wiregrass
- Completed - Inspected
- Completed - Ready for Inspection
- Repair Needed
- No Repair Needed
- Unknown
- Completed - Inspected
- Completed - Ready for Inspection
- In Progress
- Repair Needed
- Unknown
- FS - Suitable for Passenger Car
- ATV Redundant Drop Line

N  
W  
S  
E  
NW10  
9/29/2021 2055

North American 1983 Datum.  
Lat,Long Grid

