



CEDAR CREEK
Suppression Repair
OR-WIF-220180
10/20/2022 24 Hour

126,222 acres
 10/18/2022 @ 1815
 Acres determined
 from IR

North American 1983

- Drop Point
- Value at Risk
- Other
- Gate
- Water Development or Draft Site
- Structure Wrap
- Stream Crossing
- Road Repair
- Resource Location
- Repair Point
- Landing or Log Deck
- Dozer Push
- Culvert
- Safety Zone
- Other Property
- Pump
- Water Tank
- ⊗ Completed Dozer Line
- ⊗ Completed Fuel Break
- ⊗ Completed Hand Line
- ⊗ Completed Mixed Construction Line
- ⊗ Completed Road as Line
- ⊗ Planned Dozer Line
- ⊗ Planned Hand Line
- Access or Improved Road
- Retardant Drop
- Repair Line
- Road Repair
- Interior Roads
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments

Note: This map and associated tables have been filtered to only show Repair Points / Lines of Medium or High priority. There exists numerous other features of unknown or low priority repair needs throughout the fire area. The intended use of this map is to define/represent the repair work to be completed during IMT12 oversight of this incident. This map should **NOT** be considered a complete source for repair information.