


Suppression Repair

Sturgill
OR-WWF-000334
10/17/22

21,710 acres at 10/5/22 2306 PDT

- | | | |
|---|--|--|
| <ul style="list-style-type: none"> Other Property Pump Water Tank Dip Site Helispot Incident Command Post Drop Point Closure Other Gate Structure Wrap Road Repair Repair Point Hazard Tree | <ul style="list-style-type: none"> Dozer Push Culvert Repeater Water Source Completed Dozer Line Completed Fuel Break Completed Mixed Construction Line Completed Road as Line Access or Improved Road Other Road Repair Uncontained Wildfire Daily Fire Perimeter | <ul style="list-style-type: none"> In Use - Fire Management Repair Needed Completed - Ready for Inspection Other - See Comments Repair Needed In Progress Completed - Ready for Inspection Paved Road Gravel Road, Suitable for Passenger Car Dirt Road, Suitable for Passenger Car Road, Not Maintained for Passenger Car National Forest System Roads closed to motorized uses |
|---|--|--|



SA Blue GIS
10/16/2022 2256
North American 1983 Datum,
LatLong Grid