


# Suppression Repair

Sturgill  
OR-WWF-000334  
10/19/22

22,981 acres at 10/17/22 1404 PDT

- |   |   |  |   |
|---|---|--|---|
| <ul style="list-style-type: none"> <li>Other Property</li> <li>Pump</li> <li>Water Tank</li> <li>Dip Site</li> <li>Helispot</li> <li>Incident Command Post</li> <li>Drop Point</li> <li>Closure</li> <li>Lookout</li> <li>Value at Risk</li> <li>Other</li> <li>Landmark</li> </ul> | <ul style="list-style-type: none"> <li>Gate</li> <li>Structure Wrap</li> <li>Road Repair</li> <li>Repair Point</li> <li>Hazard Tree</li> <li>Dozer Push</li> <li>Culvert</li> <li>Clean Up Area</li> <li>Mobile Weather Unit</li> <li>Repeater</li> <li>Water Source</li> <li>Completed Dozer Line</li> </ul> | <ul style="list-style-type: none"> <li>Completed Fuel Break</li> <li>Completed Mixed Construction Line</li> <li>Completed Road as Line</li> <li>Planned Hand Line</li> <li>Access or Improved Road</li> <li>Other</li> <li>Road Repair</li> <li>Uncontained</li> <li>Wildfire Daily Fire Perimeter</li> <li>In Use - Fire Management</li> <li>Repair Needed</li> </ul> | <ul style="list-style-type: none"> <li>Completed - Ready for Inspection</li> <li>Other - See Comments</li> <li>Repair Needed</li> <li>In Progress</li> <li>Completed - Ready for Inspection</li> <li>Paved Road</li> <li>Gravel Road, Suitable for Passenger Car</li> <li>Dirt Road, Suitable for Passenger Car</li> <li>Road, Not Maintained for Passenger Car</li> <li>National Forest System Roads closed to motorized uses</li> </ul> |
|---|---|--|---|



USFS, USNPS  
10/18/2022 2136  
North American 1983 Datum,  
Lat/Long Grid