Repair

Anvil Div A
OR-RSF-000413
10/18/2023

22,170 acres at 10/01/2023 2111

0 0.5 1
Miles

124°26.0'W 124°24.0'W 124°22.0'W 124°20.0'W

42°46.0'N 42°44.0'N

ROGUE RIVER-SISKIYOU NATIONAL

Dip Site
Helispot
Sling Site
Division Break
Drop Point
Closure
Value at Risk
Other
Landmark
Gate
Bridge
Repair Point
Landing or Log Deck
Hazard Tree
Dozer Push
Culvert
Mobile Weather Unit
Repeater
Hazard
Water Source
Other Property
Pump
Water Tank
Completed Dozer Line
Completed Hand Line
Completed Mixed Construction Line
Completed Road as Line
Access or Improved Road
Road Repair
Contained
In Use - Fire Management
Needs Assessment
Repair Needed
In Progress
Completed - Ready for Inspection
Completed - Inspected
Other - See Comments
In Use - Fire Management
Needs Assessment
Repair Needed
In Progress
Completed - Ready for Inspection
Completed - Inspected
No Repair Needed
Avoidance Area
Administrative FS Boundary
Ranger District Boundary
FS Wilderness
Coquille Lands
Bureau of Land Management (BLM)
US Forest Service (USFS)

Airbus,USGS,NGA