


# REPAIR

## ANVIL DIV Z OR-RSF-000413 10/19/2023

22,170 ACRES AT 10/01/2023 2111



Dip Site	Culvert	Completed - Ready for Inspection
Helispot	Mobile Weather Unit	Completed - Inspected
Sling Site	Repeater	Other - See Comments
Division Break	Hazard	Needs Assessment
Drop Point	Water Source	Repair Needed
Closure	Other Property	In Progress
Lookout	Pump	Completed - Ready for Inspection
Value at Risk	Water Tank	Completed - Inspected
Other	Completed Dozer Line	No Repair Needed
Gate	Completed Hand Line	Administrative FS Boundary
Bridge	Completed Road as Line	Ranger District Boundary
Water Development or Draft Site	Access or Improved Road	FS Wilderness
Stream Crossing	Road Repair	BLM Area of Critical Environmental Concern
Road Repair	Contained	Bureau of Land Management (BLM)
Repair Point	In Use - Fire Management	State
Landing or Log Deck	Needs Assessment	US Fish and Wildlife Service (USFWS)
Hazard Tree	Repair Needed	US Forest Service (USFS)
Dozer Push	In Progress	