Suppression Repair - Filtered

Umpqua Fires

Chilcoot

10/05/2023

0 0.25 0.5 1 1.5
Miles









Incident Name	Map Method	Acres	Effective Date Time
Chilcoot	Mixed Methods	1940	9/23/2023 10:35:00 PM

Event Point Repair Status
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed

Other - See Comments

Event Line Repair Status
- In Use - Fire Management
- Needs Assessment
- Repair Needed
- In Progress
- Completed - Ready for Inspection
- Completed - Inspected
- No Repair Needed
- Other - See Comments
- Drop Point
- Stream Crossing
- Road Repair
- Repair Point
- Landing or Log Deck
- Dozer Push
- Culvert
- Contained
- Uncontained Fire Edge
- Completed Dozer Line
- Completed Hand Line
- Completed Road as Line
- Access or Improved Road
- Repair Line
- Closed Road
- Fire Area
- Roadless Area
- Bureau of Land Management (BLM)
- US Forest Service (USFS)

NW Team 13
10/4/2023 1402
Mixed Methods
North American 1983 Datum, LatLong Grid

North Umpqua, Oregon National Wild and Scenic River

122°48'W 122°47'W 122°46'W 122°45'W 122°44'W 122°43'W 122°42'W 122°41'W 122°40'W 122°39'W 122°38'W
43°26'N 43°25'N 43°24'N 43°23'N 43°22'N 43°21'N