



Repair

Repair

Lookout

ORWIF-230327
10/13/2023
25,754 acres at 10/04/2023 @ 1940
Acres from IR & GPS

<ul style="list-style-type: none"> ○ In Use - Fire Management Needs Assessment ● Repair Needed ○ In Progress ○ Completed - Ready for Inspection ○ Completed - Inspected ○ No Repair Needed ○ Other - See Comments ○ In Use - Fire Management Needs Assessment 	<ul style="list-style-type: none"> ■ Completed - Inspected ■ No Repair Needed ■ Other - See Comments ■ In Use - Fire Management Needs Assessment 	<ul style="list-style-type: none"> — Repair Needed — In Progress — Completed - Ready for Inspection — Completed - Inspected — No Repair Needed 	<ul style="list-style-type: none"> Other - See Comments Airstrip or Airport Dip Site Mobile Retardant Base Helispot Sling Site 	<ul style="list-style-type: none"> Unimproved Landing Area Incident Command Post Drop Point Closure Camp Staging Area 	<ul style="list-style-type: none"> Value at Risk Other Gate Bridge Water Development or Draft Site Structure Wrap 	<ul style="list-style-type: none"> ■ Stream Crossing ■ Road Repair ■ Resource Location ■ Repair Point ■ Landing or Log Deck ■ Hazard Tree 	<ul style="list-style-type: none"> ■ Fence - Cut/Damaged ■ Dozer Push ■ Culvert ■ Clean Up Area ■ Mobile Weather Unit ■ Repeater 	<ul style="list-style-type: none"> Safety Zone Hazard Contained Completed Burnout Completed Dozer Line Completed Fuel Break 	<ul style="list-style-type: none"> Completed Hand Line Completed Mixed Construction Line Completed Road as Line Retardant Drop Planned Dozer Line Access or Improved Road 	<ul style="list-style-type: none"> Other Repair Line Road Repair UAS Launch and Recovery Zone Wildfire Daily Fire Perimeter 	<ul style="list-style-type: none"> Cadore Timber Co Franklin-Clarkson Timber Co LLC Giustina (Winberry) Oregon Dept of State Lands Weyerhaeuser Timber Holdings Inc
---	--	---	---	---	---	---	--	---	---	--	--







10/13/2023 2024
North American 1983 Datum, Lat/Long Grid



Repair