



SUPPRESSION REPAIR - SOUTH

COWLITZ COMPLEX

WA-GPF-001297

9/21/2023

- In Use - Fire Management
- Completed - Inspected
- Other Property
- Water Tank
- Dip Site
- Helispot
- Sling Site
- Division Break
- Incident Command Post
- Drop Point
- Closure
- Staging Area
- Lookout
- Value at Risk
- Other
- Landmark
- Gate
- Fire Station
- Bridge
- Road Repair
- Resource Location
- Repair Point
- Dozer Push
- Culvert
- Mobile Weather Unit
- Internet Access
- Repeater
- Safety Zone
- Hazard
- Water Source
- In Use - Fire Management
- Needs Assessment
- Completed - Ready for Inspection
- No Repair Needed
- Completed Dozer Line
- Completed Hand Line
- Completed Road as Line
- Access or Improved Road
- State
- Other
- Repair Line
- Road Repair
- Escape Route
- Contained
- Uncontained
- Wildfire Daily Fire Perimeter
- Forest Service Wilderness
- Bureau of Indian Affairs (BIA)
- Bureau of Land Management (BLM)
- State
- US Fish and Wildlife Service (USFWS)
- US Forest Service (USFS)

Repair Status	Feature Category	Total Length (ft)
Completed - Inspected	Access or Improved Road	564
Completed - Inspected	Completed Dozer Line	876
Completed - Inspected	Completed Hand Line	1,711
Completed - Ready for Inspection	Completed Hand Line	114
In Progress	Completed Dozer Line	1,357
In Use - Fire Management	Access or Improved Road	440,814
In Use - Fire Management	Completed Dozer Line	10,367
In Use - Fire Management	Completed Hand Line	11,446
In Use - Fire Management	Completed Road as Line	66,609

Repair Status	Feature Category	Total Length (ft)
In Use - Fire Management	Escape Route	5,902
In Use - Fire Management	Other	173,562
In Use - Fire Management	Repair Line	19,999
In Use - Fire Management	Road Repair	151,292
Needs Assessment	Road Repair	341,912
No Repair Needed	Access or Improved Road	42,953
No Repair Needed	Other	12,688
Other - See Comments	Other	8,593
Repair Needed	Completed Hand Line	4,286

1:82,000
Map Updated: 9/20/2023 21:15