



Apalachicola National Forest Hurricane Michael Response FL-FNF-018011 Timber Group Map 10/21/2018



Major Roads

- Principal Arterial
- Major Collector
- Minor Arterial
- Minor Collector
- Local

Forest Roads

- 5 - High Degree Of User Comfort
- 4 - Moderate Degree Of User Comfort
- 3 - Suitable For Passenger Cars
- 2 - High Clearance Vehicles
- 2 - High Clearance Vehicles (Admin Only)
- 1 - Basic Custodial Care (Closed)

Forest Roads Status 10/19/18 @ 0700

- Not Passable - Needs Clearing
- Not Accessible - Debris Needs Clearing
- Passible - Needs Debris Removal
- Good

Forest Road Status Aerial Survey 10/19/18

- High Damage
- Moderate Damage
- Low Damage
- County Road
- Bridges

- Compartments
- Timber Sale Units
- GNA Compartment 25 Stands
- NEPA Project Area Stands
- Big Gully NEPA Stands
- County Boundary (Florida)
- Forest Boundary (Unofficial)
- Forest Service Land (Unofficial)

OWNER

- Private
- State

Level one Trauma Center AND Burn Unit:
Shands at the University of Florida
(29 28.20' N -82 20.33' W)

Level one Trauma Center ONLY:
Shands Jacksonville TraumaOne
(30 20.58' N -81 39.36' W)

This map was produced by the SA Red Team GIS on 10/20/2018 at 2117 Hours.

This product is reproduced from geospatial information prepared by the U.S. Department of Agriculture, Forest Service. GIS data and product accuracy may vary. They may be developed from sources of differing accuracy, accurate only at certain scales, based on modeling or interpretation, incomplete while being created or revised, etc. Using GIS products for purposes other than those for which they were created may yield inaccurate or misleading results. The Forest Service reserves the right to correct, update, modify, or replace GIS products without notification.

For more information, contact: Apalachicola National Forest
(850) 926-3561, 57 Taff Drive, Crawfordville, FL 32327.

Data Projection:
NAD_1983_StatePlane_Florida_North_FIPS_0903_Feet

