



OBJECTID	Label	Comments	Point Date/Time	Collector Name	Rehab Status
21	Culvert 3	Replace culvert. 2287 (Roads East Comments). Culvert was marked as needed replaced prior to Roads E. Assuming Culvert Collapsed and was filled with dirt. At the moment hard to tell condition	4/27/2017 6:21:15 PM	CBS	Rehab Needed
44	Culvert needed on Stokes Rd	N End of culvert on the Stokes Rd. (Rd #18 DP-18) significantly eroded due to rain event on 5/24. Will need some fill and grading repair. Culvert looks fine. 526. Fill put around culvert. Looks good.	5/25/2017 2:31:11 PM	Roads E. Casey	Rehab Complete
60	Culvert 1. T Model	Burned out culvert. Larger diameter (2 ft). Burned to Plastic culvert	5/25/2017 4:40:35 PM	Roads East. Casey	Rehab Needed
61	Culvert 2. Dog Pen Break/Turkey Rd	Burned out culvert. Larger diameter (2 ft).	5/25/2017 5:08:58 PM	Roads East. Casey	Rehab Needed
62	Culvert 4. On perimeter Rd	Culvert on perimeter road. Some damage may have been done by road repair (not sure). Steel culvert that is collapsing on the East side of road	5/25/2017 5:21:22 PM	Roads E. Casey	Rehab Needed
64	Culvert 5. On perimeter road. Collapsed and filled	This culvert on the perimeter road was collapsed due to traffic, and filled in by roads crew as a temporary fix. Needs a new culvert		Roads E. Casey	Rehab Needed
65	Culvert 6. Perimeter Rd	Portion of culvert collapsed.		Roads E. Casey	Rehab Needed
66	Culvert 7. Perimeter road	West end of culvert is rotted out has a hole. May need repair, but is not a priority at this point. Have engineer check		Roads E. Casey	Rehab Needed
76	Culvert 1. Collapsed and filled over top	Culvert appears to have collapsed and had fill added over the top. Need a new 32" long CMP pipe with 24" diameter > Non-Asphalt material pipe for replacement		Roads East	Rehab Needed

- ★ Culverts (ObjectID)
- Drop Point
- Helispot
- Aerial Hazard
- Dip Site
- Rehab Needed
- Rehab in Progress
- Rehab Complete
- Branch Break
- Division Break
- Uncontrolled Fire Edge
- Completed Line
- Completed Dozer Line
- R - R - Road as Completed Line
- Escape Route
- Completed Burnout
- Fire Access Road
- Shelters
- Swamp Edge Break
- Refuge Island
- Bethesa State Forest (FL)
- Wilderness_Bndry
- ONWR Bndry
- Logging Operations
- Highway
- Major Road
- Local Road
- Minor Road
- Other Road
- Mature Pine Stands
- Reserved Timberlands

West Mims Fire
GA-OKR 017006
5/31/2017

152,515 ac.
Perimeter as of
5/26/2017 0320 Hrs

Div M / N / O
Suppression Repair Map

