




Repair

May 16-17, 2025 Tornado
Daniel Boone NF
London RD

June 5, 2025

0 0.25 0.5 0.75 1
Miles



1:20,000 | DBNF GIS | 6/5/2025 1509

North American 1927 Datum. Lat/Long Grid

Type	Repair Status	Total Feet	Total Miles
Road Repair	Repair Needed	3562	0.67
Road Repair	Needs Assessment	4529	0.86
Road Repair	In Progress	8767	1.66
Road Repair	Completed - Inspected	457396	86.63

- Tornado Damage Path

Cold Hill Timber Sale

Cold Hill Rx Burn Perimeters

Cane Creek Timber Sale

Peters Branch Timber Sale

Rock Creek RNA

Fish Trap/Cane Creek Rx Burn Perimeters

Kentucky Department of Fish and Wildlife Resources

Office of Kentucky Nature Preserves

The Nature Conservancy

Other Designation

Helispot

Unimproved Landing Area

Drop Point

Closure

Staging Area

Value at Risk

Other

Stream Crossing

Road Repair

Culvert
- Road Repair

Sheltowee
- Repair Status

In Use - Fire Management

Needs Assessment

Repair Needed

In Progress

Completed - Ready for Inspection

Completed - Inspected

No Repair Needed

Repair Deferred

Other - See Comments
- Road By Maintenance Level

1 - BASIC CUSTODIAL CARE (CLOSED)

2 - HIGH CLEARANCE VEHICLES

3 - SUITABLE FOR PASSENGER CARS

4 - MODERATE DEGREE OF USER COMFORT

5 - HIGH DEGREE OF USER COMFORT

