

Suppression Repair Map

Division G


Mangum

AZ-KNF-000359

7/4/2020 Day

71,450 acres at 6/30/2020 2348

✕ Closure	Structure Wrap	✎ Aerial Hazard	Other - See Comments
○ Culvert	Water Source	Temporary Flight Restriction	Unknown
◆ Dip Site	Other	Repair Line	Completed - Ready for Inspection
● Drop Point	Division Break	Road Repair	In Progress
■ Dozer Push	Contained Line	Management Action Point	Repair Needed
⊕ Fence - Cut/Damaged	Completed Dozer Line	Planning Area	No Repair Needed
● Helispot	H - H - Hand Line (Completed)	Completed - Inspected	Unknown
⊕ Internet Access	n - n - Road as Completed Line	In Use - Fire Management	Range Allotments
⊕ Landing or Log Deck	Access or Improved Road	Completed - Ready for Inspection	IR Legend
⊕ Mobile Weather Unit	Line Break Completed	Repair Needed	Heat Perimeter
⊕ Repair Point	Completed Burnout	No Repair Needed	Timber Sales
⊕ Road Repair			WildHorse/TS_CutUnits_075309



B Kirk
7/3/2020 2119
North American 1983 Datum, LatLong Grid

