


Suppression Repair Map

Mangum


AZ-KNF-000359

7/8/2020 Day

71,450 acres at 6/30/2020 2348



- Camp
- Closure
- Culvert
- Dip Site
- Drop Point
- Dozer Push
- Fence - Cut/Damaged
- Helispot
- Internet Access
- Landing or Log Deck
- Mobile Weather Unit
- Repair Point
- Repeater
- Road Repair
- Safety Zone
- Structure Wrap
- Water Source
- Value at Risk
- Other
- Division Break
- Completed Dozer Line
- Hand Line (Completed)
- Access or Improved Road
- Line Break Completed
- Completed Burnout
- Aerial Hazard
- Temporary Flight Restriction
- Repair Line
- Road Repair
- Management Action Point
- Planning Area
- Completed - Inspected
- In Use - Fire Management
- Repair Needed
- No Repair Needed
- Other - See Comments
- Unknown
- Completed - Inspected
- No Repair Needed
- Unknown
- Range Allotments
- Timber Sales
- IR Legend
- Heat Perimeter



B Kirk
7/7/2020 1758
North American 1983 Datum, LatLong Grid

